Oil Field Environmental Incident Summary

Date/Time of Notice: 07/30/2014 22:58 Incident: 20140730225818 Responsible Party: STATOIL OIL & GAS LP Well Operator: STATOIL OIL & GAS LP Well Name: MELISSA 31-30 #3TFH Field Name: EAST FORK Well File #: 24755 Date Incident: 7/29/2014 Time Incident: 20:00 Facility ID Number: **WILLIAMS** Rna: 100 Sec: 31 Qtr: County: **Twp:** 156 Location Description: Submitted By: Keith Bryan Received By: Russell Rankin Contact Person: 6300 BRIDGE POINT PKY, BLDG 2 SUITE 500 AUSTIN, TX 78730 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 1 Mile Distance Nearest Occupied Building: Distance Nearest Water Well: Type of Incident: Other Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units **Followup Units Barrels** Oil 1 **Barrels** 1 **Brine** Other **Description of Other Released Contaminant:**

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Multiple ignition sources with the presence of LEL gases and hydrocarbons.

Areal Extent:

N/A

Potential Environmental Impacts:

None at this time.

Action Taken or Planned:

Oil and gas was detected coming from the base of the well head which is contained to the cellar area. All operations were immediately shut down and notifications made. Gas detection equipment is being utilized on location as well as a tank truck being utilized to capture the oil as it collects at the cellar. All ignition sources have been removed at this time and the incident has been isolated.

Wastes Disposal Location: Recovered oil will be placed back into the crude oil tanks on location. No disposal.

Agencies Involved:

Updates

Date: 7/31/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from the wellhead, remained on location, according to the report. NDIC retains oversight.